



Assignment of FISCHBACH SPEED CONTROLLERS/-AUTOMATIC CONTROLLERS

High Efficiency Fans		Automatic Control		Control		Control			
				stepless		stepwise			
				with casing, with control knob and scale		with casing			stepped switch loose
	with stepped switch	without							
Type	1)	Type	Part No.	Type	Part No.	Type	Part No.	Part No.	Part No.
Three Phase 400 V 3N~ 50 Hz									
HE 500/D 2	4,8	FRA 55/3	6281	FDR 55/3	6231	FDR 5.5/3	6172	6192	6952
HE 560/D 2.5	8,2	FRA 120/3	6283	FDR 120/3	6233	FDR 11.3/5	6175	6194	6952
HE 630/ D 5	16,1	FRA 200/3	6285	FDR 200/3	6235	FDR 20/3	6177	6197	6952
HD 500/D 2.5	8,8	FRA 120/3	6283	FDR 120/3	6233	FDR 11.3/5	6175	6194	6952
HD 560/D 5	15,9	FRA 200/3	6285	FDR 200/3	6235	FDR 20/3	6177	6197	6952
HD 630/D 5	14,2	FRA 200/3	6285	FDR 200/3	6235	FDR 20/3	6177	6197	6952
HD 630/TD 10	29,5	FRA 400/3	6287	FDR 400/3	6237	FDR 40/3	6179	6199	6952

Please note: 1) Maximum running current. This is the detail for selection of fuses and controllers.

Motor Protection: Three Phase motors are equipped with **thermo-contacts**. Our guarantee is only valid if the thermo-contact is connected through a manual cut-out interlock in the contactor.
When thermal cut-out occurs, the cause must be established and corrected.



Save energy by correct selection of fans